




# Soldering Techniques



- LSU rev20250822



# Safety Precautions





- Prior to assembly or any work, a clean and organized workstation is vital for safety and proper assembly
- Soldering Irons are extremely hot; do not touch the tip, and place the iron in a stand when not in use
- Always wear Safety Glasses while soldering
- Be mindful of where the solder might drip and where your body is relative to the iron
  - Tie back long hair
  - Wear long pants
- Wash your hands after handling leaded solder



# Safety (for the components)



- Excessive heat can damage components and boards
  - Set your iron to an appropriate temperature for the solder you are using
- Electrostatic discharge (ESD) can destroy or damage sensitive components.
  - Leave components in static shielding bags until ready for use
  - Use ESD wrist straps to ground yourself while working





# Tips for Success



- Use bright enough lighting to see the board and component marking
- Install smaller components first
- Install integrated circuits (IC's) into sockets, not directly on the board
- Choose a solder thickness and tip size appropriate to the component you are working with
- It's easier to add solder or re-melt than remove excess solder





# Types of Solder



- **Leaded solders**
  - Primarily Lead and Tin
  - Starts melting ~350F
- **Lead Free Solder**
  - Lead-free but higher melting temperature (~420F)
  - Can be more difficult to work
- **Solder Paste**
  - Paste in syringe
  - Use for surface mounting component soldering with hot air or ovens
- **Solder flux**
  - Rosin flux helps the solder flow and stick onto the PCB pads
  - Many solders have flux inside the solder, will be labelled “Rosin Core:





# Soldering Irons



- Constant Power Soldering Irons
  - Iron continuously heats and eventually reaches equilibrium temperature
- Constant temperature
  - Tip heats to maintain a preset temperature
- Temperature Controlled Solder Station
  - Adjustable Temperature Setting
  - Often includes a temperature display



30-watt Constant Power Iron




Temperature Controlled Solder Station



# Soldering Tutorial Through-Hole Component





- Due to its high temperature, the iron tip will rapidly form an oxidation layer that slows heat transfer
- It will take a darker, dull appearance
- Frequently during usage, “Tin” the tip
- Melt a small amount of solder on the tip and then clean the tip on the sponge or metal scour
- The tip should look shiny





# Identify component pads and orientation



- Locate the pads for the component by finding the identifier on the silkscreen of the board
  - This is often a few letters and a number, for example, D301 for diode 301 to the right
  - Check the schematic if markings are unclear
- Look for orientation or pin numbering marks
  - In the best case, the markings will be obvious, like lining the diode strip with the line on the board to the right
  - But sometimes markings may be ambiguous or have changed since the board was designed
  - Incorrectly installed components will not function properly and may damage other components in the circuit



Proper installed diode and integrated circuit

# Install the Component

- Insert the component's leads through the holes in the circuit board
  - Most components should lie flush against the surface of the board
  - Do not force the component down as you may break a lead
- Fix the component in place and flip the board over
  - Bending the component leads outward can help hold the component in place
  - Tape can also be used to hold components down, just be careful not to tape the metal leads, which will get hot during soldering






# Heat Pads and Apply Solder



- Apply the iron in contact with both the circuit board pad and the component lead
  - The iron should be in contact with both so both heated
- Apply solder to the joint, not to the iron, and allow the heated joint to melt the solder
  - The solder should follow onto both the pad and the lead
- You want a “Hershey kiss” of solder when you are done










# Inspect the solder

Inspect the solder joints. It should be uniform and shiny, with no cracks, gaps, or graininess. The images below are examples of good soldering.






# Bad Solder Joints




# Trimming Leads

- If solder is good trim the excess leads using a pair of diagonal cutters
- When cutting hold the lead so it does not go flying when snapped
- Avoid cutting into the solder joint itself; the mechanical force could peel the pad off the board
  - The goal is prevent leads from being able to create shorts, not trim a flat surface



# Solder Pump

- If you need to remove excessive solder or remove a soldered component, one technique is a solder pump
- A solder pump, or “solder sucker,” removes liquid solder from the board with a small spring-operated vacuum




Solder Pump



# Using a solder pump

- Compress the spring by pushing the priming handle down until you hear a click
- Heat the excess solder until it becomes molten
- Place the tip of the solder pump near or on the joint and press the suction release
- The spring will push the plunger up and suck some of the solder into the pump
- Eject the solder out of the pump by pressing down the priming handle
- You may need to repeat to remove the desired amount of solder



Removing excess solder by sucking it up with a solder pump.





# Solder Wick



- Solder wick is copper braid that usually comes in spools
- When the wick is heated, excess solder will naturally flow up the wick
- To use:
  - Place the wick on top of the joint to be desoldered
  - Heat the wick by pressing it into the solder with the iron
  - The will flow onto the wick
  - Remove the iron and with wick from the joint simultaneously
    - If you allow the solder to cool, the wick will stick to the joint and potentially pull the pad away from the board as you pull the wick
  - A length of wick will now have solder on it, cut this off the spool and dispoe



Spool of Solder Wick



# Removing Components



- For multipin components, it is very difficult to remove enough solder to completely remove it at once
- It is usually better to sacrifice the component by cutting its leads
- Then the remaining pins can be removed one at a time
- This will avoid damaging the traces on the circuit board, which are very difficult to repair